

Waiting for input signal.....

Received Measure Control start signal.

4 characters received from NMC-->PASS

Waiting for input signal.....

Received Assay Start signal.

28 characters received from Symmetry-->Symmetry: 0.0552, 9.919

Symmetry difference is 0.055200

Symmetry Sigma is 9.919000

25 characters received from Pu600-->PU600: 0.0623, 7.431

Pu600 ratio is 0.062300 percent is 7.431000

25 characters received from Pu900-->PU900: 416.000, 4.903

Pu900 area is 416.000000 percent is 4.903000